




# MOODY METHODIST CHURCH

## 2021 MOODY STEEPLE CLADDING REPAIRS

### WEEKLY FIELD REPORT NO. 01

### WEEK OF 1/18/2021

#### Weekly Weather



Date: Monday, January 18, 2021

On Site:	Coltzer Company, LLC Betco Scaffolds	Temperature – Low/High (°F):	48/64
		Rain (Total Inches):	0.00"
		Max Wind Speed(mph):	17 SE
Field Note:	Comments & Photographs:		
01 18-01	<i>Coltzer Company, LLC</i> on site to observe steeple repairs progress.		
01 18-02	<i>Betco Scaffolds</i> begins erecting scaffolding on the south side of the sanctuary. (see photo01-06)		



Photo01: Preparing for Scaffolding



Photo02: Scaffolding Unloaded from the Truck



Photo03: Scaffolding Being Assembled



Photo04: Scaffolding Being Assembled



Photo05: Scaffolding Being Assembled



Photo06: Scaffolding Material Laid Out

**Date: Tuesday, January 19, 2021**

<b>On Site:</b>	Coltzer Company, LLC	<b>Temperature – Low/High (°F):</b>	61/70
	Betco Scaffolding	<b>Rain (Total Inches):</b>	0.00
		<b>Max Wind Speed(mph):</b>	17 SE
<b>Field Note:</b>	<b>Comments &amp; Photographs:</b>		
<b>01 19-01</b>	<i>Coltzer Company, LLC</i> on site to observe steeple repairs progress.		
<b>01 19-02</b>	<i>Betco Scaffolding</i> continues erecting scaffolding on the south side of the sanctuary. (see photo07-10)		



Photo07: Scaffolding Being Assembled



Photo08: Scaffolding Being Assembled



Photo09: Scaffolding Being Assembled



Photo10: 53rd Street View of Scaffolding

**Date: Wednesday, January 20, 2021**

<b>On Site:</b>	Coltzer Company, LLC Betco Scaffolding	<b>Temperature – Low/High (°F):</b>	59/63
		<b>Rain (Total Inches):</b>	0.00
		<b>Max Wind Speed(mph):</b>	11 E
<b>Field Note:</b>	<b>Comments &amp; Photographs:</b>		
<b>01 20-01</b>	<i>Coltzer Company, LLC</i> on site to observe steeple repairs progress.		
<b>01 20-02</b>	<i>Betco Scaffolding</i> continues erecting scaffolding on the south side of the sanctuary. <i>(see photo11-14)</i>		



Photo11: Scaffolding Being Assembled



Photo12: Scaffolding Being Assembled



Photo13: Lift Brought in to Help Assemble Scaffolding



Photo14: Lift Used to Carry Up Scaffolding Equipment

Date: Thursday, January 21, 2021

On Site:	Coltzer Company, LLC	Temperature – Low/High (°F):	63/70
		Rain (Total Inches):	0.00"
		Max Wind Speed(mph):	11 SSW

Field Note: **Comments & Photographs:**

**01 21-01** *Coltzer Company, LLC* on site to observe steeple repairs progress.

**01 21-02** *Betco Scaffolding* continues erecting scaffolding on the south side of the sanctuary. Scaffold supports are placed on the roof of the sanctuary. (see photo15-18)




Photo15: Scaffold Supports on Foam and Plywood



Photo16: Scaffolding Being Assembled Above Roof



Photo17: Scaffold Supports Being Placed on Roof of Sanctuary



Photo18: Scaffold Supports Being Placed on Roof of Sanctuary

**Date: Friday, January 22, 2021**

<b>On Site:</b>	Coltzer Company, LLC Mann's Carpentry RB Hash	<b>Temperature – Low/High (°F):</b>	46/63
		<b>Rain (Total Inches):</b>	0.00
		<b>Max Wind Speed(mph):</b>	17 S
<b>Field Note:</b>	<b>Comments &amp; Photographs:</b>		
<b>01 22-01</b>	<i>Coltzer Company, LLC</i> on site to observe steeple repairs progress.		
<b>01 22-02</b>	<i>Betco Scaffolding</i> continues erecting scaffolding on the south side of the sanctuary. Scaffold supports are placed on the roof of the sanctuary. Chain link fence is placed around the scaffolding. ( <i>see photo19-22</i> )		



**Photo19: Scaffolding Being Assembled on Roof**



**Photo20: Scaffolding Assembled on Roof**



**Photo21: Scaffolding Assembled on Roof**



**Photo22: Chain Link Fence Around Scaffolding**

**DISTRIBUTION LIST**

NAME	REPRESENTING	PHONE NUMBER	E-MAIL
Bill Coltzer	Coltzer Company, LLC	409-740-0090	<a href="mailto:bcoltzer@z6consulting.com">bcoltzer@z6consulting.com</a>
Lidija Bikova	Zero/Six Consulting, LLC	409-740-0090	<a href="mailto:LBikova@z6consulting.com">LBikova@z6consulting.com</a>
Richard Parks	Coltzer Company, LLC	470-314-2821	<a href="mailto:rparks@z6consulting.com">rparks@z6consulting.com</a>
Sam Caminade	Moody Church	409-771-7785	<a href="mailto:sam@moody.com">sam@moody.com</a>
Bryan Hash	R.B. Hash Roofing		<a href="mailto:rbh@rbhash.com">rbh@rbhash.com</a>
John Garza	R.B. Hash Roofing		<a href="mailto:jgarza@rbhash.com">jgarza@rbhash.com</a>
Justin Wenner	Betco Scaffolding		<a href="mailto:justin.wenner@scaffold.com">justin.wenner@scaffold.com</a>
Steve Grimes	Betco Scaffolding		<a href="mailto:steve.grimes@scaffold.com">steve.grimes@scaffold.com</a>

*The preceding represents Coltzer Company's understanding of the principal matters discussed and/or observed. Written comments with regard to the content of this report should be received by Coltzer Co. within three days from date of issue. After that date, these notes shall stand as a final accounting of the items discussed and/or observed.*